ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0043	NA	Vinayaka layout 3rd Cross Roads
Segment No.	**Total Length (m)**	
1/S-W0043/S033411	82.14	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	82.14	77.611126	13.118729	77.611018	13.117994	W0038	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Constructions of Drains at Vinayaka layout 3rd Cross Roads in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	800000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	DRAIN
Tender	**Work Details**	**Job No. / Work Code**
Tender	Constructions of Drains at Vinayaka layout 3rd Cross Roads in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	001-17-000016
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D)E-PMT-08/WO/27/2017-18	02/05/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
31/05/2017	30/05/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
A.KUMAR REDDY		0.00
Phone No.	**E-Mail ID**	
9900997067		

Field Inspection Details

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0043

Date: 18/06/2017 Time: 16:33:27 RH 20170618163327

nber of Trees

10

Any Other Information

Name

SACHIN

Date of Inspection

18/06/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	18/06/2017	18/07/2017	COMPLETED
SE	VASU K M	18/06/2017	18/07/2017	COMPLETED
EE	VASU K M	18/06/2017	18/07/2017	COMPLETED
AEE	DEVARAJ	18/06/2017	18/07/2017	COMPLETED
AE	SACHIN	18/06/2017	18/07/2017	COMPLETED
AE	SACHIN	18/06/2017	18/07/2017	COMPLETED